## ANALYTICAL REPORT

TestAmerica Laboratories, Inc.

TestAmerica Richland 2800 George Washington Way Richland, WA 99352 Tel: (509)375-3131

TestAmerica Job ID: 300-3246-1

TestAmerica Sample Delivery Group: WC1149

Client Project/Site: F16-043

or:

CH2M Hill Plateau Remediation Company PO BOX 1600 Mail Stop R3-50 Richland, Washington 99352

Attn: CPP Sample Management

Str apon

Authorized for release by: 7/6/2016 10:28:23 AM
Steven Campbell, Project Mgmt. Assistant steven.campbell@testamericainc.com

Designee for

Whitney Ritari, Project Manager I (509)375-3131 ext164 whitney.ritari@testamericainc.com

LINKS

Review your project results through

Total Access

**Have a Question?** 



Visit us at: www.testamericainc.com

I certify that this Certificate of Analysis is in compliance with the SOW, both technically and for completeness, for other than the conditions detailed in this package. Release of the data contained in this hard copy data package has been authorized by the Laboratory Manager, or a desingee as verified by the attached signature.

The laboratory is accredited to EPA 7196A in Solid and Chemical Materials, per Washington State Department of Ecology this is approved for non-discharge water samples. The sample/sample duplicate RPD agreement is not applicable if one or both results are less than five times the MDL.

2

3

4

6

10

12

1,

Client: CH2M Hill Plateau Remediation Company Project/Site: F16-043

TestAmerica Job ID: 300-3246-1 SDG: WC1149

# **Table of Contents**

Cover Page	1
Table of Contents	2
Definitions/Glossary	3
Case Narrative	4
Chain of Custody	5
Detection Summary	6
Client Sample Results	7
QC Sample Results	8
QC Association Summary	9
Lab Chronicle	10
Method Summary	12
Sample Summary	13
Receipt Checklists	14

2

3

4

6

8

11

12

13

### **Definitions/Glossary**

Client: CH2M Hill Plateau Remediation Company

Project/Site: F16-043

**Quality Control** 

Relative error ratio

Toxicity Equivalent Factor (Dioxin)

Toxicity Equivalent Quotient (Dioxin)

Reporting Limit or Requested Limit (Radiochemistry)

Relative Percent Difference, a measure of the relative difference between two points

TestAmerica Job ID: 300-3246-1

SDG: WC1149

#### **Qualifiers**

#### **General Chemistry**

Qualifier	Qualifier Description
U	Analyzed for but not detected.
D	The reported value is from a dilution.

#### **Glossary**

QC

RER

RPD

TEF

TEQ

RL

Abbreviation	These commonly used abbreviations may or may not be present in this report.
¤	Listed under the "D" column to designate that the result is reported on a dry weight basis
%R	Percent Recovery
CFL	Contains Free Liquid
CNF	Contains no Free Liquid
DER	Duplicate error ratio (normalized absolute difference)
Oil Fac	Dilution Factor
DL, RA, RE, IN	Indicates a Dilution, Re-analysis, Re-extraction, or additional Initial metals/anion analysis of the sample
DLC	Decision level concentration
MDA	Minimum detectable activity
EDL	Estimated Detection Limit
MDC	Minimum detectable concentration
MDL	Method Detection Limit
ML	Minimum Level (Dioxin)
IC	Not Calculated
ND	Not detected at the reporting limit (or MDL or EDL if shown)
PQL	Practical Quantitation Limit

#### **Case Narrative**

Client: CH2M Hill Plateau Remediation Company

Project/Site: F16-043

TestAmerica Job ID: 300-3246-1

SDG: WC1149

Job ID: 300-3246-1

Laboratory: TestAmerica Richland

**Narrative** 

**Job Narrative** 300-3246-1

#### Comments

No additional comments.

#### Receipt

The sample was received on 6/9/2016 1:55 PM; the sample arrived in good condition, properly preserved and, where required, on ice. The temperature of the cooler at receipt was 6.9° C.

#### **General Chemistry**

No analytical or quality issues were noted, other than those described in the Definitions/Glossary page.

PRINTED ON 6/9/2016

FSR ID = FSR32674

**TRVL NUM = TRVL-16-153** 

A-6003-618 (REV 2)

5 of 14 7/6/2016

DATE/TIME		DISPOSED BY				DISPOSAL METHOD	FINAL SAMPLE DISPOSITION
DATE/TIME		TITLE				RECEIVED BY	LABORATORY SECTION
			DATE/TIME	RECEIVED BY/STORED IN	DATE/TIME	REMOVED FROM	RELINQUISHED BY/REMOVED FROM
300-3246 COC			DATE/TIME	RECEIVED BY/STORED IN	DATE/TIME	REMOVED FROM	RELINQUISHED BY/REMOVED FROM
			DATE/TIME	RECEIVED BY/STORED IN	DATE/TIME	REMOVED FROM	RELINQUISHED BY/REMOVED FROM
			DATE/TIME	RECEIVED BY/STORED IN	DATE/TIME	ZEMOVED FROM	RELINQUISHED BY/REMOVED FROM
			N 0 9 2016 (355)	RECEIVED BY/STORED IN  RECEIVED BY/STORED IN	DATE/TIME 25	REMOVED FROM JUN	RELINQUISHED BY/REMOVED FROM LEMY WEST CHERGE RELINQUISHED BY/REMOVED FROM
ENSURE ADEQUATE PORTION SAMPLES	YSIS; SAMPLE A AND B	SPLIT SPOON PARTS B & A WILL BE COMBINED TO ENSURE ADEQUATE SAMPLE MATERIAL FOR ANALYSIS; SAMPLE A AND B PORTION SAMPLES B35VP6 B35VP7 V35VP8	JUN 0 900 TIME	Wall		SEMONED FROM	RELINQUISHED BY/REMOVED FROM
		SPECIAL INSTRUCTIONS	<b>-</b>	SIGN/ PRINT NAMES		NOIS	CHAIN OF POSSESSION
				CC30 SICE GOND		SOIL	B35VP7
				ATE SAMPLE TIME	MATRIX*	-	SAMPLE NO.
		A1-76	9	SAMPLE ANALYSIS COMMON;	D/OR STORAGE	SPECIAL HANDLING AND/OR STORAGE	-
		>C\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	·	VOLUME . 60mL			V=Vegetation W=Water
		S	ارد ارد ارد ارد ارد ارد ارد ارد ارد ارد	NO. OF CONTAINER(S)			S=Soil SE=Sediment T=Tissue
				TYPE OF CONTAINER G/P	not releasable per	Goods Regulations but are not releasable per DOE Order 458.1. NA	
			ays	HOLDING TIME 30 Days	t be regulated for IATA Dangerous	concentrations that are not be regulated for transportation per 49 CFR/IATA Dangerous	#
			Cool <=6C	-	ARDS/ REMARKS	POSSTBLE SAMPLE HAZARDS/ REMARKS *Contains Radioactive Material at	
	4	2		こう		TestAmerica Incorporated, Richland	TestAmerica Inc
	-	BILL OF LADING/AIR BILL NO.	·	-			SHIPPED TO
ORIGINAL	GOVERNMENT VEHICLE	<b>COA</b> 304070	66.50 - 109.0	チンゴー ひ・G45-シータG			でと CHESI NO.
15 Days / 15 Days	AIR QUALITY	NO.		PROJECT DESIGNATION  100-NR-2 Drilling - Soil		NOI	SAMPLING LOCATION C9401, I-004
DATA TURNAROUND	PRICE CODE 8C	TODAK, D	376-6427	TODAK, D		ЖC	J.R. Aguilar/CHPRC
PAGE 1 OF 1	F16-043-038	REQUEST COORDINATOR	CHAIN OF CUSTODY/SAMPLE ANALYSIS REQUEST		n Company	CH2MHill Plateau Remediation Company	COLLECTOR
)							

## **Detection Summary**

Client: CH2M Hill Plateau Remediation Company

Project/Site: F16-043

TestAmerica Job ID: 300-3246-1

SDG: WC1149

Client Sample ID: B35VP7 Lab Sample ID: 300-3246-1

No Detections.

## **Client Sample Results**

Client: CH2M Hill Plateau Remediation Company

Project/Site: F16-043

TestAmerica Job ID: 300-3246-1

SDG: WC1149

Client Sample ID: B35VP7 Lab Sample ID: 300-3246-1

Date Collected: 06/09/16 08:30 Matrix: Soil Date Received: 06/09/16 13:55

**General Chemistry** Analyte Result Qualifier RLMDL Unit D Prepared Analyzed Dil Fac Cr (VI) 0.15 U 2.0 0.15 mg/Kg 06/28/16 16:39 06/20/16 18:04

#### QC Sample Results

Client: CH2M Hill Plateau Remediation Company

Project/Site: F16-043

TestAmerica Job ID: 300-3246-1

SDG: WC1149

Method: 7196A - Chromium, Hexavalent

Lab Sample ID: MB 300-4724/1-A

Lab Sample ID: LCS 300-4724/2-A

**Matrix: Solid** 

**Analysis Batch: 4723** 

Client Sample ID: Method Blank

Prep Type: Total/NA

Prep Batch: 4724

мв мв

Result Qualifier RL MDL Unit Analyte D Prepared Analyzed Dil Fac 2.0 Cr (VI) 0.15 U 0.15 mg/Kg 06/28/16 16:39 06/20/16 17:48

Client Sample ID: Lab Control Sample

Prep Type: Total/NA

**Matrix: Solid** 

**Analysis Batch: 4723** 

Prep Batch: 4724 Spike LCS LCS

Added Analyte Result Qualifier Unit %Rec Limits Cr (VI) 20.0 18.12 mg/Kg 91 85 - 115

Lab Sample ID: 300-3142-A-1-F MS Client Sample ID: Matrix Spike

**Matrix: Solid** 

**Analysis Batch: 4723** 

Prep Type: Total/NA

Prep Batch: 4724

%Rec.

Sample Sample Spike MS MS Result Qualifier Added Analyte Result Qualifier Unit D %Rec Limits Cr (VI) 0.15 U 29.8 25.82 87 75 \_ 125 mg/Kg

Client Sample ID: Matrix Spike Lab Sample ID: 300-3142-A-1-H MSI

**Matrix: Solid** 

**Analysis Batch: 4723** 

Prep Type: Total/NA

35

Prep Batch: 4724

%Rec.

Sample Sample Spike MSI MSI Analyte Result Qualifier Added Result Qualifier Unit %Rec Limits Cr (VI) 0.15 U 674 695.3 D 103 mg/Kg

Lab Sample ID: 300-3142-A-1-G DU **Client Sample ID: Duplicate** 

**Matrix: Solid** 

**Analysis Batch: 4723** 

Prep Type: Total/NA Prep Batch: 4724 RPD

DU DU Sample Sample Analyte Result Qualifier Result Qualifier RPD Limit Unit 0.15 U Cr (VI) 0.15 U NC mg/Kg

TestAmerica Richland

## **QC Association Summary**

Client: CH2M Hill Plateau Remediation Company

Project/Site: F16-043

TestAmerica Job ID: 300-3246-1

SDG: WC1149

#### **General Chemistry**

#### Analysis Batch: 4723

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
300-3142-A-1-F MS	Matrix Spike	Total/NA	Solid	7196A	4724
300-3142-A-1-G DU	Duplicate	Total/NA	Solid	7196A	4724
300-3142-A-1-H MSI	Matrix Spike	Total/NA	Solid	7196A	4724
300-3246-1	B35VP7	Total/NA	Soil	7196A	4724
LCS 300-4724/2-A	Lab Control Sample	Total/NA	Solid	7196A	4724
MB 300-4724/1-A	Method Blank	Total/NA	Solid	7196A	4724

#### Prep Batch: 4724

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
300-3142-A-1-F MS	Matrix Spike	Total/NA	Solid	3060A	
300-3142-A-1-G DU	Duplicate	Total/NA	Solid	3060A	
300-3142-A-1-H MSI	Matrix Spike	Total/NA	Solid	3060A	
300-3246-1	B35VP7	Total/NA	Soil	3060A	
LCS 300-4724/2-A	Lab Control Sample	Total/NA	Solid	3060A	
MB 300-4724/1-A	Method Blank	Total/NA	Solid	3060A	

#### **Lab Chronicle**

Client: CH2M Hill Plateau Remediation Company

Project/Site: F16-043

TestAmerica Job ID: 300-3246-1

SDG: WC1149

**Matrix: Solid** 

TAL RCH

Client Sample ID: B35VP7 Lab Sample ID: 300-3246-1 Date Collected: 06/09/16 08:30

Matrix: Soil

06/28/16 16:39

TDA

Date Received: 06/09/16 13:55

	Batch	Batch		Dil	Initial	Final	Batch	Prepared		
Prep Type	Туре	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab
Total/NA	Analysis	7196A		1	2.5023 g	100 mL	4723	06/20/16 18:04	TDA	TAL RCH
Total/NA	Prep	3060A			2.5023 g	100 mL	4724	06/28/16 16:39	TDA	TAL RCH

**Client Sample ID: Duplicate** Lab Sample ID: 300-3142-A-1-G DU

Date Collected: 05/25/16 14:00

Date Received: 05/26/16 16:00

	Batch	Batch		Dil	Initial	Final	Batch	Prepared		
Prep Type	Type	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab
Total/NA	Analysis	7196A		1	2.5107 g	100 mL	4723	06/20/16 17:53	TDA	TAL RCH
Total/NA	Prep	3060A			2.5107 g	100 mL	4724	06/28/16 16:39	TDA	TAL RCH

Client Sample ID: Lab Control Sample Lab Sample ID: LCS 300-4724/2-A

Date Collected: N/A **Matrix: Solid** 

Date Received: N/A

3060A

Prep

Batch Dil Initial Final Batch Batch Prepared Prep Type Туре Method Run Factor Amount Amount Number or Analyzed Analyst Lab Total/NA Analysis 7196A 2.5 g 100 mL 4723 06/20/16 17:49 TDA TAL RCH

Client Sample ID: Method Blank Lab Sample ID: MB 300-4724/1-A

2.5 g

100 mL

4724

Date Collected: N/A Matrix: Solid

Date Received: N/A

Total/NA

	E	Batch	Batch		Dil	Initial	Final	Batch	Prepared		
Prep T	уре Т	Гуре	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab
Total/N	NA A	Analysis	7196A		1	2.5 g	100 mL	4723	06/20/16 17:48	TDA	TAL RCH
Total/N	NA F	Prep	3060A			2.5 g	100 mL	4724	06/28/16 16:39	TDA	TAL RCH

Client Sample ID: Matrix Spike Lab Sample ID: 300-3142-A-1-F MS

Date Collected: 05/25/16 14:00 **Matrix: Solid** 

Date Received: 05/26/16 16:00

	Batch	Batch		Dil	Initial	Final	Batch	Prepared		
Prep Type	Type	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab
Total/NA	Analysis	7196A		1	2.5116 g	100 mL	4723	06/20/16 17:52	TDA	TAL RCH
Total/NA	Prep	3060A			2.5116 g	100 mL	4724	06/28/16 16:39	TDA	TAL RCH

Client Sample ID: Matrix Spike Lab Sample ID: 300-3142-A-1-H MSI

Date Collected: 05/25/16 14:00 Matrix: Solid

Date Received: 05/26/16 16:00

	Batch	Batch		Dil	Initial	Final	Batch	Prepared		
Prep Type	Type	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab
Total/NA	Analysis	7196A		20	2.5066 g	100 mL	4723	06/20/16 17:54	TDA	TAL RCH
Total/NA	Prep	3060A			2.5066 g	100 mL	4724	06/28/16 16:39	TDA	TAL RCH

TestAmerica Richland

### **Lab Chronicle**

Client: CH2M Hill Plateau Remediation Company

Project/Site: F16-043

Laboratory References:

TAL RCH = TestAmerica Richland, 2800 George Washington Way, Richland, WA 99352, TEL (509)375-3131

TestAmerica Job ID: 300-3246-1

SDG: WC1149

3

5

7

8

10

лл

12

13

## **Method Summary**

Client: CH2M Hill Plateau Remediation Company

Project/Site: F16-043

TestAmerica Job ID: 300-3246-1

SDG: WC1149

Method	Method Description	Protocol	Laboratory
7196A	Chromium, Hexavalent	SW846	TAL RCH

#### **Protocol References:**

SW846 = "Test Methods For Evaluating Solid Waste, Physical/Chemical Methods", Third Edition, November 1986 And Its Updates.

TAL RCH = TestAmerica Richland, 2800 George Washington Way, Richland, WA 99352, TEL (509)375-3131

## **Sample Summary**

Client: CH2M Hill Plateau Remediation Company

Project/Site: F16-043

TestAmerica Job ID: 300-3246-1

SDG: WC1149

Lab Sample ID	Client Sample ID	Matrix	Collected	Received
300-3246-1	B35VP7	Soil	06/09/16 08:30	06/09/16 13:55

3

4

5

R

9

10

12

13

### **Login Sample Receipt Checklist**

Client: CH2M Hill Plateau Remediation Company

Job Number: 300-3246-1

SDG Number: WC1149

Login Number: 3246 List Source: TestAmerica Richland

List Number: 1 Creator: Bock, Julie A

Question	Answer	Comment
Radioactivity wasn't checked or is = background as measured by a survey meter.</td <td>True</td> <td></td>	True	
The cooler's custody seal, if present, is intact.	N/A	
Sample custody seals, if present, are intact.	True	
The cooler or samples do not appear to have been compromised or tampered with.	True	
Samples were received on ice.	True	
Cooler Temperature is acceptable.	True	
Cooler Temperature is recorded.	True	
COC is present.	True	
COC is filled out in ink and legible.	True	
COC is filled out with all pertinent information.	True	
Is the Field Sampler's name present on COC?	True	
There are no discrepancies between the containers received and the COC.	True	
Samples are received within Holding Time (excluding tests with immediate HTs)	True	
Sample containers have legible labels.	True	
Containers are not broken or leaking.	True	
Sample collection date/times are provided.	True	
Appropriate sample containers are used.	True	
Sample bottles are completely filled.	True	
Sample Preservation Verified.	True	
There is sufficient vol. for all requested analyses, incl. any requested MS/MSDs	True	
Containers requiring zero headspace have no headspace or bubble is <6mm (1/4").	N/A	
Multiphasic samples are not present.	N/A	
Samples do not require splitting or compositing.	True	
Residual Chlorine Checked.	N/A	